

Katun Performance™ Drum Unit Rebuild Kit for use in

Konica Minolta bizhub PRO C5500/C5501/C6500/C6501/C65hc-series

MFPs

Katun PN: 43588 • OEM PN: N/A
 (Applications use 4 drum unit rebuild kits – CMYK)

You can count on cost-per-copy savings and consistent image quality with this Katun Performance™ drum unit rebuild kit!



Benefits:

- ◆ Improve overall profitability by reducing your cost-per-copy
- ◆ OEM-equivalent image quality and performance
- ◆ Fits and performs in equivalent Develop, IKON and Océ PLD models
- ◆ Easy to rebuild

This drum unit rebuild kit allows the servicing dealer to rebuild used OEM drum units, reducing environmental waste. The rebuild process is easy and can be completed in about 15 minutes or less. Detailed, illustrated, step by step instructions can be found online at www.katun.com in the Resources/Install & Rebuild section.

Product Characteristics

Metrics	OEM	Katun
Part number	Drum Unit: A0400Y4 (DU-102C)	Rebuild Kit: 43588
Price per/sold in	Priced and sold per drum unit	Priced and sold per rebuild kit
Master carton quantity	8 drum units per master carton	4 rebuild kits per master carton
Kit contents	N/A	(1) OPC Drum (1) Drum Cleaning Blade (1) Lubrication Bar (1) Cleaning Unit Seal - Left (1) Cleaning Unit Seal - Right (2) Drum Cleaning Blade Tension Spring
Photoreceptor stated life*	150,000 copies (C5500/C5501-series) 200,000 copies (C6500/C6501-series)	150,000 copies (C5500/C5501-series) 200,000 copies (C6500/C6501-series)
Country of origin	China	Kit assembled in Mexico
OPC Color	Green	Green

*Actual life may vary depending on machine application, machine condition, and usage conditions.

13-09-6659 © 2013 Katun Corporation

Note: As with the OEM drum unit, the Katun Performance™ drum unit rebuild kit is “universal” – it can be used for any of the color positions within this four-drum system. The convenient Katun master carton is easier to store and transport with four Katun Performance™ drum unit rebuild kits inside.